MicroNet™ Position Control Module Product Obsolescence

Product Change / Improvement

The MicroNet™ Position Control Module family is going obsolete. The modules will be inactivated by 31 July 2015. For customers specifically wanting additional spares of the Position Control module, Woodward is offering a Last Time Buy (LTB) opportunity. Repair services will be available up to 5 years after module inactivation, depending on component availability. Please see the Obsolete Modules section below for the affected item numbers.

Obsolete Modules

Obsolete MicroNet Position Control Modules

Part Number	Description
5466-030	Module - Position Controller EM
5466-344	Module - Position Controller EM DFB
5466-345	Module - Position Controller EM SFB
5501-461	Module - Position Controller TM DFB
5501-462	Module - Position Controller TM SFB

Updated Products

Users of the Position Control Module should contact Woodward or a Woodward Authorized Distributor for potential upgrade solutions.

Customer Action

If you require additional Position Control modules, please order Last Time Buy units by 31 July 2015.

For additional information and support:
1. Contact your local Woodward representative and/or turbine OEM.
2. Woodward contact and business partner information can be obtained at **www.woodward.com**.
3. Technical assistance can be obtained by:
   a. Searching for a local contact at **www.woodward.com/directory**
   b. Call or email the Woodward Turbine Help Desk:
      1-970-498-3095
      TurbineHelpDesk@woodward.com

W WOODWARD