

#### **Woodward GmbH**

Handwerkstr. 29 70565 Stuttgart - Germany Tel: +49 (0) 711 789 54-0 Fax: +49 (0) 711 789 54-100 www.woodward.com/power

15-June-2011

# Notification of easYgen-3000/RP-3000 part number transition to new part numbers





We received information from our display suppliers that the monochrome displays for the easYgen-3000 Series are discontinued due to the Tsunami in Japan, which has destroyed the facility of a display component sub supplier.

Based on this fact we are now forced to install color displays in all easYgen-3000 derivates and RP-3000 Remote panels.

#### Remote panel strategy:

- Woodward will standardize on only one part number for the RP-3000 which will be equipped with a color display by standard
- Each RP-3000 Remote panel will in future be delivered with a CD-ROM that includes the flash update files to turn it into either a RP-3200-P1, RP-3200-P2 or RP-3500-P1 Remote panel.

#### Advantages:

- Color display by standard in all easYgen-3000 derivates and RP-3000 Remote Panels
- Only one part number for the RP-3000
- Distributors and Customers just need to put one RP-3000 Remote Panel on stock and by flashing the corresponding update files it can be turned into a Remote panel that fits to each easYgen-3000 derivate

### New Software functionality in RP-3000 Remote panels:

■ The Remote panel software will be updated so that the RP-3000 Remote Panel automatically detects whether it has the correct software installed that fits to the connected easYgen-3000 derivate. If the RP-3000 Remote panel and easYgen-3000 software do not match to each other a message on the RP-3000 display will be shown.



# Part number changes:

- Woodward will create new part numbers for all easYgen-3000 units, including easYgen-3000/RP-3000 with customized faceplates as well.
- Please see part number transition table in section "Part numbers to be inactivated and corresponding replacement part numbers".

#### Planned date for transition to the new part numbers:

- The transition to color displays is planned for September-2011.

# Part numbers to be inactivated and corresponding replacement part numbers:

The part numbers in this column will become inactive on 31-Dec- 2011		Replacement part numbers available in Sept-2011	
<b>Item Number</b>	Description	<b>Item Number</b>	Description
8440-1922	EASYGEN-3200-1/P1	8440-2049	EASYGEN-3200-1/P1
8440-1923	EASYGEN-3200-5/P1	8440-2050	EASYGEN-3200-5/P1
8440-1924	EASYGEN-3200-1/P2	8440-2051	EASYGEN-3200-1/P2
8440-1925	EASYGEN-3200-5/P2	8440-2052	EASYGEN-3200-5/P2
8440-1927	EASYGEN-3200-5/P1	8440-2053	EASYGEN-3200-5/P1
8440-1930	EASYGEN-3100-5/P1	8440-2054	EASYGEN-3100-5/P1
8440-1931	EASYGEN-3100-1/P1	8440-2055	EASYGEN-3100-1/P1
8440-1932	EASYGEN-3100-5/P2	8440-2056	EASYGEN-3100-5/P2
8440-1933	EASYGEN-3100-1/P2	8440-2057	EASYGEN-3100-1/P2
8440-1979	EASYGEN-3200-5/P1	8440-2062	EASYGEN-3200-5/P1
8440-1980	EASYGEN-3200-5/P2	8440-2063	EASYGEN-3200-5/P2
8440-1992	EASYGEN-3200-5/P1	8440-2064	EASYGEN-3200-5/P1
8440-1993	EASYGEN-3200-5/P1	8440-2065	EASYGEN-3200-5/P1
8440-1994	EASYGEN-3200-5/P2	8440-2066	EASYGEN-3200-5/P2
8440-1995	EASYGEN-3200-5/P2	8440-2067	EASYGEN-3200-5/P2
8440-1996	EASYGEN-3200-5/P2	8440-2068	EASYGEN-3200-5/P2
8440-1997	EASYGEN-3100-1/P2	8440-2069	EASYGEN-3100-1/P2
8440-2026	EASYGEN-3200-5/P2	8440-2070	EASYGEN-3200-5/P2
8440-2033	EASYGEN-3200-1/P2	8440-2071	EASYGEN-3200-1/P2
8446-1018	RP-3200-P1	8446-1048	RP-3000
8446-1019	RP-3200-P2	8446-1048	RP-3000
8446-1022	RP-3200-P1	8446-1050	RP-3200-P1
8446-1030	RP-3200-P2	8446-1051	RP-3200-P2
8446-1031	RP-3200-P2	8446-1052	RP-3200-P2
8446-1032	RP-3200-P2	8446-1053	RP-3200-P2
8446-1042	RP-3500-P1	8446-1048	RP-3000
8446-1043	RP-3200-P1	8446-1055	RP-3200-P1
8446-1044	RP-3200-P1	8446-1056	RP-3200-P1



# Old easYgen-3000 Part numbers that will be inactivated :

The following old easYgen-3000 part numbers will be inactivated on 30-Sept-2011:

These part numbers will be				
discontinued on 30-Sept-2011				
Item Number ▼				
8440-1816	EASYGEN-3200-1			
8440-1817	EASYGEN-3100-5			
8440-1818	EASYGEN-3100-1			
8440-1831	EASYGEN-3200-5			
8440-1842	EASYGEN-3200-1/P2			
8440-1843	EASYGEN-3200-5/P2			
8440-1844	EASYGEN-3100-1/P2			
8440-1845	EASYGEN-3100-5/P2			
8440-1848	EASYGEN-3200-5			
8440-1876	EASYGEN-3200-5/K25			
8440-1902	EASYGEN-3200-5/K25			
8440-1908	EASYGEN-3200-5			
8440-1910	EASYGEN-3200-5/K27			
8440-1911	EASYGEN-3200-5/P2			
8440-1915	EASYGEN-3200-1/K25			
8440-1943	EASYGEN-3200-5/P2			
8440-1964	EASYGEN-3200-5/P2			
8440-1965	EASYGEN-3200-5/K27			
8440-1974	EASYGEN-3100-1/P2			
8446-1014	EASYGEN-3209- B			
8446-1017	EASYGEN-3209- B			
8446-1024	EASYGEN-3209- B			
8446-1027	EASYGEN-3209- B/P2			

Best regards Woodward GmbH

Markus Harsani

Power Generation Product Line Manager