

## Product Rationalization of PD - System Line Products

28. March 2013

This announcement is used to inform Woodward Customers, Channel Partners and Sales & Marketing of the product rationalization and product support plan for the PD – Power Distribution product lines manufactured in Woodward Kempen/Germany.

The rationalization affects the following product line variants

- Discontinued variants  
CSP2F5  
CSP2L2 (with 20km fibre optic communication interface)  
CSP2T25

Not effected product line variants

- Continued variants  
CSP2L1  
CMP1120

### Woodward offers the following “Last Time Buy” scenario for the discontinued items:

- Orders for the Last Time Buy can be placed until 1<sup>st</sup> August 2013.  
Woodward will accept orders until this date.
- Woodward will ship items ordered before the LTB date until 1<sup>st</sup> of October 2013 based on the LTB volumes. After this date Woodward will stop the production.

### Woodward will commit to the following product line support plan for the discontinued items:

#### **28<sup>th</sup> March 2013 – 31<sup>th</sup> July 2013:**

- Unlimited New Sales
- Unlimited Repairs

#### **1<sup>st</sup> August 2013 - 31<sup>th</sup> March 2014:**

- Limited Repairs based on parts availability


Parts obsolescence from electronic manufacturers can present a challenge to post-life support plans. Woodward strives to hold inventory, or look for alternative parts when components are obsolete. However, there are times when components can simply not be obtained and where sufficient last-time buys cannot be made. In these cases, Woodward cannot always guarantee that we can maintain the rationalization support plan.

**Discontinued Items:**

Item No	Extended Item No	Item Description	Comments
CSP2F5SCC00G	CSP2-F5SCC00G	PROTECTION DEVICE	Replacement by MCA4D0AA
CSP2F5SCC00E	CSP2-F5SCC00E	PROTECTION DEVICE	Replacement by MCA4D0AA
CSP2F5SCC3FG	CSP2-F5SCC3FG	PROTECTION DEVICE	Replacement by MCA4D0AF
CSP2F5SCC3FE	CSP2-F5SCC3FE	PROTECTION DEVICE	Replacement by MCA4D0AF
CSP2F5SCC3WG	CSP2-F5SCC3WG	PROTECTION DEVICE	Replacement by MCA4D0AG
CSP2F5SCC3WE	CSP2-F5SCC3WE	PROTECTION DEVICE	Replacement by MCA4D0AG
CSP2F5SCC3WEK	CSP2-F5SCC3WEK	PROTECTION DEVICE	Replacement by MCA4D0AG
CSP2F5SCCPFG	CSP2-F5SCCPFG	PROTECTION DEVICE	Replacement by MCA4D0AD
CSP2F5SCCPFGK	CSP2-F5SCCPFGK	PROTECTION DEVICE	Replacement by MCA4D0AD
CSP2F5SCCPWG	CSP2-F5SCCPWG	PROTECTION DEVICE	Replacement by MCA4D0AE
CSP2F5SCCPWE	CSP2-F5SCCPWE	PROTECTION DEVICE	Replacement by MCA4D0AE
CSP2F5SCCPWEK	CSP2-F5SCCPWEK	PROTECTION DEVICE	Replacement by MCA4D0AE
CSP2F5SCCMWE	CSP2-F5SCCMWE	PROTECTION DEVICE	Replacement by MCA4D0AG
CSP2L2SCC00G	CSP2-L2SCC00G	PROTECTION DEVICE	No replacement
CSP2L2SCC3FG	CSP2-L2SCC3FG	PROTECTION DEVICE	No replacement
CSP2L2SCC3FE	CSP2-L2SCC3FE	PROTECTION DEVICE	No replacement
CSP2L2SCC3WG	CSP2-L2SCC3WG	PROTECTION DEVICE	No replacement
CSP2L2SCC3WE	CSP2-L2SCC3WE	PROTECTION DEVICE	No replacement
CSP2L2SCCPWEK	CSP2-L2SCCPWEK	PROTECTION DEVICE	No replacement
CSP2L2SCCMFE	CSP2-L2SCCMFE	PROTECTION DEVICE	No replacement
CSP2L2SCCMWE	CSP2-L2SCCMWE	PROTECTION DEVICE	No replacement

Item No	Extended Item No	Item Description	Comments
CSP2T25SCC00G	CSP2-T25SCC00G	PROTECTION DEVICE	Replacement by MRDT4D0AA or MCDGV4A0AA
CSP2T25SCC00E	CSP2-T25SCC00E	PROTECTION DEVICE	Replacement by MRDT4D0AA or MCDGV4A0AA
CSP2T25SCC3FG	CSP2-T25SCC3FG	PROTECTION DEVICE	Replacement by MRDT4D0AF or MCDGV4A0AF
CSP2T25SCC3FGK	CSP2-T25SCC3FGK	PROTECTION DEVICE	Replacement by MRDT4D0AF or MCDGV4A0AF
CSP2T25SCC3FE	CSP2-T25SCC3FE	PROTECTION DEVICE	Replacement by MRDT4D0AF or MCDGV4A0AF
CSP2T25SCC3WG	CSP2-T25SCC3WG	PROTECTION DEVICE	Replacement by MRDT4D0AF or MCDGV4A0AF
CSP2T25SCC3WE	CSP2-T25SCC3WE	PROTECTION DEVICE	Replacement by MRDT4D0AG or MCDGV4A0AG
CSP2T25SCCPFG	CSP2-T25SCCPFG	PROTECTION DEVICE	Replacement by MRDT4D0AD or MCDGV4A0AD
CSP2T25SCCPFGK	CSP2-T25SCCPFGK	PROTECTION DEVICE	Replacement by MRDT4D0AD or MCDGV4A0AD
CSP2T25SCCPWG	CSP2-T25SCCPWG	PROTECTION DEVICE	Replacement by MRDT4D0AE or MCDGV4A0AE
CSP2T25SCCPWGK	CSP2-T25SCCPWGK	PROTECTION DEVICE	Replacement by MRDT4D0AE or MCDGV4A0AE
CSP2T25SCCPWE	CSP2-T25SCCPWE	PROTECTION DEVICE	Replacement by MRDT4D0AE or MCDGV4A0AE
CSP2T25SCCPWEK	CSP2-T25SCCPWEK	PROTECTION DEVICE	Replacement by MRDT4D0AE or MCDGV4A0AE
CSP2T25SCCMWG	CSP2-T25SCCMWG	PROTECTION DEVICE	Replacement by MRDT4D0AG or MCDGV4A0AG
CSP2T25SCCMWGK	CSP2-T25SCCMWGK	PROTECTION DEVICE	Replacement by MRDT4D0AG or MCDGV4A0AG
CSP2T25SCCMWE	CSP2-T25SCCMWE	PROTECTION DEVICE	Replacement by MRDT4D0AG or MCDGV4A0AG
CSP2T25SCCMFE	CSP2-T25SCCMFE	PROTECTION DEVICE	Replacement by MRDT4D0AF or MCDGV4A0AF
CSP2T25SCCMWEK	CSP2-T25SCCMWEK	PROTECTION DEVICE	Replacement by MRDT4D0AG or MCDGV4A0AG

Best regards



**Woodward Kempen GmbH**

Volker Dörschug

Woodward Kempen GmbH

Product Line Manager

P: +49 2152 145-325 | F: +49 2152 145-200

[volker.doerschug@woodward.com](mailto:volker.doerschug@woodward.com)

[www.woodward.com](http://www.woodward.com)