

8 January 2010

Product Rationalization of PD - Power Distribution Products

This announcement is used to inform Woodward PGD sales teams and channel partners of the product rationalization and support plan for the PD – Power Distribution product lines.

This product rationalization should minimize the extensive variants of items and define supersets of part numbers with reduced functionality.

The rationalization regards to the following device lines

- 1 Voltage Regulator / Modules**
- 2 Basic Line**
- 3 Function Line**
- 4 Professional Line**
- 5 High Tech Line**
- 6 WI – Line**
- 7 System Line**
- 8 HighPROTEC**
- 9 Power Protection Aux.**

Some products in the device lines will be discontinued completely

- 1 Basic Line**
BV1
- 2 High Tech Line**
MRD1
MRK1
IRI1
IRD1
- 3 WI – Line**
WI1
- 4 System Line**
CSP2F3 will be replaced by CSP2F5

Two different parts are defined

- Parts to be discontinued with LTB and production stop
- Parts set to inactive directly

Definition of items as parts to be discontinued

Part numbers which have been sold in very low run or shall be replaced by part numbers with maximum/more functionality. E.g. WIC12P can be replaced by WIC12PE.

Last Time Buy (LTB) stop

We defined one date for all discontinued part numbers which can be ordered until this date.

LTB stop on 30 April 2010 (no further sales order are accepted)

We defined one date for all discontinued part numbers which should be shipped until this date.

Production stop: 31 July 2010 (no shipment after this date)

Definition of items which will be set inactive directly

Obsolete items will be inactivating immediately. These are devices which can't be manufactured anymore or were ordered last time for several years.

Definition of Replacement

The mechanical dimension and electrical function is covered to 100%

Definition of Replacement / Similar Item

Deviation in mechanical dimension or electrical function

After production support

For long-term support, Woodward SEG will provide repair services and replacement exchange units according to the following schedule:

Parts to be discontinued

Now through December 31, 2017:

Repairs based on parts availability

Replacement exchange from available Woodward SEG Service Stock

Parts set to inactive

Now through December 31, 2011:

Repairs based on parts availability

Parts obsolescence from electronic manufacturers can present a challenge to these post-life support plans. Woodward strives to hold inventory or look for alternative parts when components become obsolete. However, there are times when components simply cannot be obtained and where sufficient last-time buys cannot be made. In these cases, Woodward cannot always guarantee that we can maintain the product support plan.

With kind regards



Andre Gerits

Product Line Manager

EPS - Electrical Power Systems

PD - Power Distribution

Woodward SEG GmbH & Co.KG

Krefelder Weg 47

47906 Kempen - Germany

Tel: +49 2152 145-238

Mobile: +49 151-54436310

Fax: +49 2152 145-455

E-Mail: agerit@woodward.com

1 Voltage Regulator/ Modules

Parts to be discontinued

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
CLG1			30.04.2010	31.07.2010
CLG2VB			30.04.2010	31.07.2010
TZ122024			30.04.2010	31.07.2010

Parts set to inactive directly

Part number	Replacement	Replacement / Similar item
BLC1		
BLC1V		
CLF1		
CLG2BUSL1.5		
CLS1R		
COSIMATCT		
COSIMATL		
COSIMATL+		
COSIMATLC2SEC		
COSIMATN+T		
COSIMATN1+		
COSIMATN10+		
COSIMATN12		
COSIMATN5+		
COSIMATN6+		
COSIMATN9+		
COSTR4		
EI1		
EIW1		
ER1M		
ES1110		
ES1220		
ES180TR4		
PLAST24		
PSB1		
RS485		
SFG323060		
SR		
ST1220		
ST180		
SWU2801		
TF1400		
TR4+		
UF3		

Part number	Replacement	Replacement / Similar item
UFWK1		
UGR1		
WK11U254		BU1AC230 / XU2AC
WK12.2230STBY		BU1AC230 / XU2AC
WK12.2254		BU1AC230 / XU2AC
WK12.2440SBUF		BU1AC230 / XU2AC
ZSM215		

2 Basic Line

Parts to be discontinued

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
BI12301		XI111	30.04.2010	31.07.2010
BI1241		XI111	30.04.2010	31.07.2010
BP1R1101		BP1P1105	30.04.2010	31.07.2010
BP1R2301		BP1P2305	30.04.2010	31.07.2010
BU1DC212		BU1DC224	30.04.2010	31.07.2010
BV1110			30.04.2010	31.07.2010
BV1230			30.04.2010	31.07.2010
BV1400			30.04.2010	31.07.2010
BZ1G12		BZ1G24	30.04.2010	31.07.2010
BZ1P12		BZ1P24	30.04.2010	31.07.2010
SY2SP12750		SY2SP11050	30.04.2010	31.07.2010
SY2SP40050		SY2SP23050	30.04.2010	31.07.2010

Parts set to inactive directly

Part number	Replacement	Replacement / Similar item
BA1110		BUA1110
BA1230		BUA1230
BA1400		BUA1400
BI12305		XI115
BI1245		XI115
BIW1100		
BIW11000		
BIW120		
BIW150		
BR1PIF1S		BP1R1
BR1PIF1SE		BP1R1
SY212750		SY223050

3 Function Line

Parts to be discontinued

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
DU2612		DU2624	30.04.2010	31.07.2010
DX112			30.04.2010	31.07.2010
DX124			30.04.2010	31.07.2010
NC318P			30.04.2010	31.07.2010

Parts set to inactive directly

Part number	Replacement	Replacement / Similar item
DP2		
DU2ADAP2E		
DU2ADAP3E		
DU2ADAP4E		
DU2ADAPS		
DU2BUSL82B		
DU2BUSL83A		
DU2BUSL83B		
DU2BUSL84A		
DU2BUSL84B		
DU2BUSL8SPZ		
ED2812		ED2824
EKR1424G		
EP23224		
EP2824		
EU33224G		
EU38110G		
EU3824G		
EU3848G		
EU3860G		
FP2812		
FP2824		
GP2224		
KU1R110G		
LWR223050		
MO17LCD		
MT21812		
MT21824		
MT223224		
MT22812		
MT22824		
MT233224		
MT24824		
NC3ADAPMAT		

Part number	Replacement	Replacement / Similar item
NC3M		
NP21924		NB218
NP22924		NB218
NPADAP2E		
NPADAP3E		
NPADAP4E		
NPADAPTER		
NXE24		
PCL/PCMAP		
PSY2FU150		
PSY2FU160		
PSY2FU250		
PSY2FU260		
PSY2FU450		
PSY3FU160CBD		
PSY3FU160CBE		
PSY4/5AP		
RP224		
SS31		
SS3-2		
SS3-3		
SU38230W		
SU3824G		
SU3BUSL81A		
SU3BUSL82A		
SU3BUSL83A		
SU3BUSL84A		
SY140050		SY240050
SYSP40050		SY2SP23050
TP1		
U28110G		
U38110G		
U38230W		
U3824G		
U3848G		
U3NT23024		
ZEU33224G		
ZEU38110G		
ZEU3824G		
ZU38110G		
ZU3824G		

4 Professional Line

Parts to be discontinued

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
PLCU24			30.04.2010	31.07.2010
XA1	XUA1		30.04.2010	31.07.2010
XD1G11SP		XD1G11	30.04.2010	31.07.2010
XD1G15SP		XD1G15SAT	30.04.2010	31.07.2010
XD1G51SP		XD1G51SAT	30.04.2010	31.07.2010
XD1G55SP		XD1G55	30.04.2010	31.07.2010
XD1L11		XD1L11SP	30.04.2010	31.07.2010
XD1L55		XD1L11SP	30.04.2010	31.07.2010
XD1L55SP		XD1L11SP	30.04.2010	31.07.2010
XD1T11SP		XD1T11	30.04.2010	31.07.2010
XD1T55		XD1T11	30.04.2010	31.07.2010
XD1T55SP		XD1T11	30.04.2010	31.07.2010
XF2400			30.04.2010	31.07.2010
XRI1I1E1M		XRI1I1E1	30.04.2010	31.07.2010
XRI1I5E1		XRI1I1E1	30.04.2010	31.07.2010
XRI1I5E5M		XRI1I5E5	30.04.2010	31.07.2010
XRI1I5R2		XRI1I5R4	30.04.2010	31.07.2010
XRI1X1R1		XRI1E1R1	30.04.2010	31.07.2010
XRI1X1R1M		XRI1E1R1	30.04.2010	31.07.2010
XRN212	XRN214		30.04.2010	31.07.2010
XRN222		XRN224	30.04.2010	31.07.2010
XRW127		XRW147	30.04.2010	31.07.2010
XRW131		MRA4A0AA	30.04.2010	31.07.2010
XRW137		MRA4A0AA	30.04.2010	31.07.2010
XRW141			30.04.2010	31.07.2010
XRW144	XRW147		30.04.2010	31.07.2010
XU1DC1DB			30.04.2010	31.07.2010
XU2AC400			30.04.2010	31.07.2010
XUF2400			30.04.2010	31.07.2010

Parts set to inactive directly

Part number	Replacement	Replacement /Similar item
XM11PIEF		
XM15PIEF		
XU1DC3SNL		
XUF1400INJ		

5 High Tech Line

Parts to be discontinued

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
CCPMP			30.04.2010	31.07.2010
CDS			30.04.2010	31.07.2010
HTL6M42		HTL3F42	30.04.2010	31.07.2010
HTL6M84		HTL3F843	30.04.2010	31.07.2010
HTLCU230A			30.04.2010	31.07.2010
HTLCU230D			30.04.2010	31.07.2010
IRD1G1EHA		LR20459	30.04.2010	31.07.2010
IRD1G1EHD		LR20459	30.04.2010	31.07.2010
IRD1G1ELA		LR20459	30.04.2010	31.07.2010
IRD1G1ELD		LR20459	30.04.2010	31.07.2010
IRD1G1ESATHA		LR20459	30.04.2010	31.07.2010
IRD1G1ESATHD		LR20459	30.04.2010	31.07.2010
IRD1G1ESATLA		LR20459	30.04.2010	31.07.2010
IRD1G1ESATLD		LR20459	30.04.2010	31.07.2010
IRD1G1SPHA		LR20459	30.04.2010	31.07.2010
IRD1G1SPHD		LR20459	30.04.2010	31.07.2010
IRD1G1SPLA		LR20459	30.04.2010	31.07.2010
IRD1G1SPLD		LR20459	30.04.2010	31.07.2010
IRD1G1SPSATHD		LR20459	30.04.2010	31.07.2010
IRD1G1SPSATLA		LR20459	30.04.2010	31.07.2010
IRD1G1SPSATLD		LR20459	30.04.2010	31.07.2010
IRD1G5EHA		8441-1010	30.04.2010	31.07.2010
IRD1G5EHD		8441-1010	30.04.2010	31.07.2010
IRD1G5ELA		8441-1010	30.04.2010	31.07.2010
IRD1G5ELD		8441-1010	30.04.2010	31.07.2010
IRD1G5ESATHA		8441-1010	30.04.2010	31.07.2010
IRD1G5ESATHD		8441-1010	30.04.2010	31.07.2010
IRD1G5ESATLA		8441-1010	30.04.2010	31.07.2010
IRD1G5ESATLD		8441-1010	30.04.2010	31.07.2010
IRD1G5SPHD		8441-1010	30.04.2010	31.07.2010
IRD1G5SPLD		8441-1010	30.04.2010	31.07.2010
IRD1G5SPSATHD		8441-1010	30.04.2010	31.07.2010
IRD1G5SPSATLA		8441-1010	30.04.2010	31.07.2010
IRD1G5SPSATLD		8441-1010	30.04.2010	31.07.2010
IRD1L5EHD		XD1L55SAT	30.04.2010	31.07.2010
IRD1L5ELD		XD1L55SAT	30.04.2010	31.07.2010
IRD1L5ESATHD		XD1L55SAT	30.04.2010	31.07.2010
IRD1L5SPSATHA		XD1L55SAT	30.04.2010	31.07.2010
IRD1T21EHA		LR20021	30.04.2010	31.07.2010
IRD1T21EHD		LR20021	30.04.2010	31.07.2010
IRD1T21ELA		LR20021	30.04.2010	31.07.2010
IRD1T21ELD		LR20021	30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
IRD1T21ESATHA		LR20021	30.04.2010	31.07.2010
IRD1T21ESATHD		LR20021	30.04.2010	31.07.2010
IRD1T21ESATLA		LR20021	30.04.2010	31.07.2010
IRD1T21ESATLD		LR20021	30.04.2010	31.07.2010
IRD1T21SPHD		LR20021	30.04.2010	31.07.2010
IRD1T21SPLD		LR20021	30.04.2010	31.07.2010
IRD1T21SPSATHD		LR20021	30.04.2010	31.07.2010
IRD1T21SPSATLD		LR20021	30.04.2010	31.07.2010
IRD1T25EHA		5448-897	30.04.2010	31.07.2010
IRD1T25EHD		5448-897	30.04.2010	31.07.2010
IRD1T25ELA		5448-897	30.04.2010	31.07.2010
IRD1T25ELD		5448-897	30.04.2010	31.07.2010
IRD1T25ESATHA		5448-897	30.04.2010	31.07.2010
IRD1T25ESATHD		5448-897	30.04.2010	31.07.2010
IRD1T25ESATLA		5448-897	30.04.2010	31.07.2010
IRD1T25ESATLD		5448-897	30.04.2010	31.07.2010
IRD1T25SPHD		5448-897	30.04.2010	31.07.2010
IRD1T25SPLA		5448-897	30.04.2010	31.07.2010
IRD1T25SPLD		5448-897	30.04.2010	31.07.2010
IRD1T25SPSATHD		5448-897	30.04.2010	31.07.2010
IRD1T25SPSATLD		5448-897	30.04.2010	31.07.2010
IRI13ER1HA			30.04.2010	31.07.2010
IRI13ER1HD			30.04.2010	31.07.2010
IRI13ER1LA			30.04.2010	31.07.2010
IRI13ER1LD			30.04.2010	31.07.2010
IRI13ER5HA			30.04.2010	31.07.2010
IRI13ER5HD			30.04.2010	31.07.2010
IRI13ER5LA			30.04.2010	31.07.2010
IRI13ER5LD			30.04.2010	31.07.2010
IRI1ER1HA		MRI3E1A	30.04.2010	31.07.2010
IRI1ER1LA		MRI3E1A	30.04.2010	31.07.2010
IRI1ER5HA		MRI3E5A	30.04.2010	31.07.2010
IRI1ER5LA		MRI3E5A	30.04.2010	31.07.2010
IRI1ES1HD		MRI3E1D	30.04.2010	31.07.2010
IRI1ES1LA		MRI3E5A	30.04.2010	31.07.2010
IRI1ES1LD		MRI3E5D	30.04.2010	31.07.2010
IRI1ES5HD		MRI3E5D	30.04.2010	31.07.2010
IRI1ES5LA		MRI3E5A	30.04.2010	31.07.2010
IRI1ES5LD		MRI3E5D	30.04.2010	31.07.2010
IRI1I1E01A		MRI1I5E5D	30.04.2010	31.07.2010
IRI1I1E01D		MRI1I1E1D	30.04.2010	31.07.2010
IRI1I1E05A		MRI1I5E5D	30.04.2010	31.07.2010
IRI1I1E05D		MRI1I5E5D	30.04.2010	31.07.2010
IRI1I5E01A		MRI1I5E5D	30.04.2010	31.07.2010
IRI1I5E01D		MRI1I5E5D	30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
IRI1I5E05A		MRI1I5E5D	30.04.2010	31.07.2010
IRI1I5E05D		MRI1I5E5D	30.04.2010	31.07.2010
IRI1LE5D		MRI3LE5DM	30.04.2010	31.07.2010
IRU1E1HA		XU1E	30.04.2010	31.07.2010
IRU1E1HD		XU1E	30.04.2010	31.07.2010
IRU1E1LA		XU1E	30.04.2010	31.07.2010
IRU1E1LD		XU1E	30.04.2010	31.07.2010
IRU1E2HD		XU1E	30.04.2010	31.07.2010
IRU1E2LD		XU1E	30.04.2010	31.07.2010
IRU1E4LD		XU1E	30.04.2010	31.07.2010
IRU1UO1HA		IRU1UO1HD	30.04.2010	31.07.2010
IRU1UO1LA		IRU1UO1HD	30.04.2010	31.07.2010
IRU1UO1LD		IRU1UO1HD	30.04.2010	31.07.2010
IRU1UO2HA		IRU1UO1HD	30.04.2010	31.07.2010
IRU1UO2HD		IRU1UO1HD	30.04.2010	31.07.2010
IRU1UO2LA		IRU1UO1HD	30.04.2010	31.07.2010
IRU1UO2LD		IRU1UO1HD	30.04.2010	31.07.2010
IRU1UO4HA		IRU1UO4HD	30.04.2010	31.07.2010
IRU1UO4LA		IRU1UO4HD	30.04.2010	31.07.2010
IRU1UO4LD		IRU1UO4HD	30.04.2010	31.07.2010
MRA1220D	MRA1D		30.04.2010	31.07.2010
MRA1A		MRA1D	30.04.2010	31.07.2010
MRD1FH			30.04.2010	31.07.2010
MRD1FL			30.04.2010	31.07.2010
MRD1G1HA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1G1LA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1G1MA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1G5HA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1G5LA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1G5MA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T211HA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T211LA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T211MA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T215HA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T215LA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T251HA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T251LA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T255HA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T255LA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T255MA		MRDT4A0AA	30.04.2010	31.07.2010
MRD1T2HTL3F42			30.04.2010	31.07.2010
MRD1T2HTL6M42			30.04.2010	31.07.2010
MRD1T3111HA			30.04.2010	31.07.2010
MRD1T3111LA			30.04.2010	31.07.2010
MRD1T3551HA			30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
MRD1T3551LA			30.04.2010	31.07.2010
MRD1T3555HA			30.04.2010	31.07.2010
MRD1T3555LA			30.04.2010	31.07.2010
MRD1T3HTL3F42			30.04.2010	31.07.2010
MRD1T3HTL6M42			30.04.2010	31.07.2010
MRF31AM		MRF31A	30.04.2010	31.07.2010
MRF32A		MRF31A	30.04.2010	31.07.2010
MRF32DM		MRF32D	30.04.2010	31.07.2010
MRF34A		MRF31A	30.04.2010	31.07.2010
MRF34D		MRF32D	30.04.2010	31.07.2010
MRF34DM		MRF31DM	30.04.2010	31.07.2010
MRG3A		MRG3D	30.04.2010	31.07.2010
MRG3I1E1RA		MRG3I1E1RD	30.04.2010	31.07.2010
MRG3I1U0A		MRG3I1U0D	30.04.2010	31.07.2010
MRG3I1U0AM		MRG3I1U0D	30.04.2010	31.07.2010
MRG3I1U0DM		MRG3I1U0D	30.04.2010	31.07.2010
MRG3I5E5RDM		MRG3I5E5RD	30.04.2010	31.07.2010
MRG3U0D		MRG3I1U0D	30.04.2010	31.07.2010
MRI1I1E1A		MRI3I1E1A	30.04.2010	31.07.2010
MRI1I1E1AM		MRI3I1E1A	30.04.2010	31.07.2010
MRI1I1E5A		MRI1I5E5A	30.04.2010	31.07.2010
MRI1I1E5D		MRI1I1E1D	30.04.2010	31.07.2010
MRI1I1E5DM		MRI1I5E5DM	30.04.2010	31.07.2010
MRI1I1U1A		MRI1I5U1D	30.04.2010	31.07.2010
MRI1I1U1D		MRI1I5U1D	30.04.2010	31.07.2010
MRI1I1U2A		MRI1I5U1D	30.04.2010	31.07.2010
MRI1I1U2D		MRI1I5U1D	30.04.2010	31.07.2010
MRI1I1U4A		MRI1I5U4D	30.04.2010	31.07.2010
MRI1I1U4D		MRI1I5U4D	30.04.2010	31.07.2010
MRI1I5E1A		MRI3I5E1A	30.04.2010	31.07.2010
MRI1I5E1D		MRI1I1E1D	30.04.2010	31.07.2010
MRI1I5E1DM		MRI3I5E1DM	30.04.2010	31.07.2010
MRI1I5E5A		MRI3I5E5A	30.04.2010	31.07.2010
MRI1I5E5AM		MRI3I5E5AM	30.04.2010	31.07.2010
MRI1I5U1A		MRI1I5U1D	30.04.2010	31.07.2010
MRI1I5U2A		MRI1I5U1D	30.04.2010	31.07.2010
MRI1I5U2D		MRI1I5U1D	30.04.2010	31.07.2010
MRI1I5U4A		MRI1I5U4D	30.04.2010	31.07.2010
MRI1X1R1A		MRI1I5X1R1A	30.04.2010	31.07.2010
MRI3E1AM		MRI3E1A	30.04.2010	31.07.2010
MRI3E1DM		MRI3E1D	30.04.2010	31.07.2010
MRI3E1R1A		XRI1E1R1	30.04.2010	31.07.2010
MRI3E1R1AM		MRI3I1R1E1R1A	30.04.2010	31.07.2010
MRI3E1R1D		XRI1E1R1	30.04.2010	31.07.2010
MRI3E1R1DM		MRI3I1R1E1R1D	30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
MRI3E1R2DM		MRI3I1R1E1R1D	30.04.2010	31.07.2010
MRI3E1R4D		MRI3I1R1E1R1D	30.04.2010	31.07.2010
MRI3E5AM		MRI3E5A	30.04.2010	31.07.2010
MRI3E5DM	MRI3I5E5DM		30.04.2010	31.07.2010
MRI3E5R1A		MRI3I1R1E5R1A	30.04.2010	31.07.2010
MRI3E5R1AM		MRI3I5R1E5R1D	30.04.2010	31.07.2010
MRI3E5R1D		MRI3I5R1E5R1D	30.04.2010	31.07.2010
MRI3E5R1DM		MRI3I5R1E5R1D	30.04.2010	31.07.2010
MRI3I1A	MRI3I1E1A		30.04.2010	31.07.2010
MRI3I1AM		MRI3I5E5AM	30.04.2010	31.07.2010
MRI3I1CX1R1DM		MRI3I1R1X1R1D	30.04.2010	31.07.2010
MRI3I1D	MRI3I1E1D		30.04.2010	31.07.2010
MRI3I1DM	MRI3I1E1DM		30.04.2010	31.07.2010
MRI3I1E1AM		MRI3I5E5AM	30.04.2010	31.07.2010
MRI3I1E1DAR		MRI4A0AB	30.04.2010	31.07.2010
MRI3I1E1R1A	MRI3I1R1E1R1A		30.04.2010	31.07.2010
MRI3I1E1R1AM		MRI3I1R1E1R1A	30.04.2010	31.07.2010
MRI3I1E1R1D		MRI3I1R1E1R1D	30.04.2010	31.07.2010
MRI3I1E1R1DM		MRI3I1R1E1R1D	30.04.2010	31.07.2010
MRI3I1E5DM		MRI3I5E5DM	30.04.2010	31.07.2010
MRI3I1HE1A		MRI3I1HE1D	30.04.2010	31.07.2010
MRI3I1HE1DM		MRI3I1HE1D	30.04.2010	31.07.2010
MRI3I1R1A		MRI3I1R1E1R1A	30.04.2010	31.07.2010
MRI3I1R1AM		MRI3I1R1E1R1A	30.04.2010	31.07.2010
MRI3I1R1D		MRI3I1R1E1R1D	30.04.2010	31.07.2010
MRI3I1R1DM		MRI3I1R1E1R1D	30.04.2010	31.07.2010
MRI3I1R1E1DM		MRI3I1R1E1D	30.04.2010	31.07.2010
MRI3I1R1E1R1AM		MRI3I1R1E1R1A	30.04.2010	31.07.2010
MRI3I1R1E1R1DM		MRI3I1R1E1R1D	30.04.2010	31.07.2010
MRI3I1R1S1R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I1R1S1R1DM		MRA4A0AB	30.04.2010	31.07.2010
MRI3I1R1X1R1DM		MRI3I1R1X1R1DM	30.04.2010	31.07.2010
MRI3I1R4A		MRI3I1R1E1AA	30.04.2010	31.07.2010
MRI3I1R4D		MRI3I1R1E1R1D	30.04.2010	31.07.2010
MRI3I1R4E1R4A		MRI3I1R1E1R1A	30.04.2010	31.07.2010
MRI3I1R4E1R4D		MRI3I1R1E1R1D	30.04.2010	31.07.2010
MRI3I1S1R1A		MRA4A0BB	30.04.2010	31.07.2010
MRI3I1S1R1D		MRA4A0AB	30.04.2010	31.07.2010
MRI3I1S1R1DM		MRA4A0AB	30.04.2010	31.07.2010
MRI3I1TA		MRI3I1TE1A	30.04.2010	31.07.2010
MRI3I1TD	MRI3I1TE1D		30.04.2010	31.07.2010
MRI3I1TE1DM		MRI3I1TE1D	30.04.2010	31.07.2010
MRI3I1TE1R1A		MRA4A0BB	30.04.2010	31.07.2010
MRI3I1TE1R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I1TE5R1D		MRA4A0AB	30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
MRI3I1X1R1A	MRI3I1R1X1R1A		30.04.2010	31.07.2010
MRI3I1X1R1D		MRI3I5X1R1D	30.04.2010	31.07.2010
MRI3I1X1R1DM		MRI3I1X1R1D	30.04.2010	31.07.2010
MRI3I5A	MRI3I5E5A		30.04.2010	31.07.2010
MRI3I5AM	MRI3I5E5AM		30.04.2010	31.07.2010
MRI3I5CE1DM		MRI3I5CE5DM	30.04.2010	31.07.2010
MRI3I5CE5AM		MRI3I5CE5DM	30.04.2010	31.07.2010
MRI3I5CX1DM		MRI3I5CE5DM	30.04.2010	31.07.2010
MRI3I5CX5DM		MRI3I5CE5DM	30.04.2010	31.07.2010
MRI3I5D	MRI3I5E5D		30.04.2010	31.07.2010
MRI3I5DM	MRI3I5E5DM		30.04.2010	31.07.2010
MRI3I5E1AM		MRI3I5E1A	30.04.2010	31.07.2010
MRI3I5E1R1A	MRI3I5R1E1R1A		30.04.2010	31.07.2010
MRI3I5E1R1AM		MRI3I5E1R1A	30.04.2010	31.07.2010
MRI3I5E1R1D	MRI3I5R1E1R1D		30.04.2010	31.07.2010
MRI3I5E1R1DM		MRI3I5R1E1R1D	30.04.2010	31.07.2010
MRI3I5E5DAR		MRI3I5E5D	30.04.2010	31.07.2010
MRI3I5E5R1A	MRI3I5R1E5R1A		30.04.2010	31.07.2010
MRI3I5E5R1D	MRI3I5R1E1R1D		30.04.2010	31.07.2010
MRI3I5E5R1DM		MRI3I5R1E5R1D	30.04.2010	31.07.2010
MRI3I5E5R2D		MRI3I5R1E5R1D	30.04.2010	31.07.2010
MRI3I5HE1A		MRI3I5HE5D	30.04.2010	31.07.2010
MRI3I5HE1DM		MRI3I5HE5D	30.04.2010	31.07.2010
MRI3I5HE5A		MRI3I5HE5D	30.04.2010	31.07.2010
MRI3I5HE5DM		MRI3I5HE5D	30.04.2010	31.07.2010
MRI3I5R1A		MRI3I5R1E1R1A	30.04.2010	31.07.2010
MRI3I5R1AM		MRI3I5R1E5R1A	30.04.2010	31.07.2010
MRI3I5R1D		MRI3I5R1E5R1D	30.04.2010	31.07.2010
MRI3I5R1DM	MRI3I5R1E5R1DM		30.04.2010	31.07.2010
MRI3I5R1E1DM		MRI3I5R1E1D	30.04.2010	31.07.2010
MRI3I5R1E1R1AM		MRI3I5R1E1R1A	30.04.2010	31.07.2010
MRI3I5R1E1R1DM		MRI3I5R1E1R1D	30.04.2010	31.07.2010
MRI3I5R1E5DM		MRI3I5R1E5D	30.04.2010	31.07.2010
MRI3I5R1E5R1AM		MRI3I5R1E5R1A	30.04.2010	31.07.2010
MRI3I5R1E5R1DM		MRA4A0AB	30.04.2010	31.07.2010
MRI3I5R1S1R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I5R1S5R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I5R1S5R1DM		MRA4A0AB	30.04.2010	31.07.2010
MRI3I5R1X1R1D		MRI3I1R1X1R1D	30.04.2010	31.07.2010
MRI3I5R1X1R1DM		MRI3I1R1X1R1D	30.04.2010	31.07.2010
MRI3I5R2D		MRI3I5R1E5DD	30.04.2010	31.07.2010
MRI3I5R2DM		MRI3I5R1E5D	30.04.2010	31.07.2010
MRI3I5R2E5D		MRI3I5R1E5R1D	30.04.2010	31.07.2010
MRI3I5R2E5DM		MRI3I5R1E5D	30.04.2010	31.07.2010
MRI3I5R2S5R2DM		MRA4A0AB	30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
MRI3I5R4D		MRI3I5R1E5D	30.04.2010	31.07.2010
MRI3I5R4DM		MRI3I5R1E5D	30.04.2010	31.07.2010
MRI3I5R4E1R4A		MRI3I5R1E1R1A	30.04.2010	31.07.2010
MRI3I5R4E5A		MRI3I5R1E5A	30.04.2010	31.07.2010
MRI3I5R4E5D		MRI3I5R1E5D	30.04.2010	31.07.2010
MRI3I5R4E5R4D		MRI3I5R1E5R1D	30.04.2010	31.07.2010
MRI3I5R4S5R4D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I5R4S5R4DM		MRA4A0AB	30.04.2010	31.07.2010
MRI3I5S1R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I5S1R1DM		MRA4A0AB	30.04.2010	31.07.2010
MRI3I5S5R1A		MRA4A0BB	30.04.2010	31.07.2010
MRI3I5S5R1AM		MRA4A0BB	30.04.2010	31.07.2010
MRI3I5S5R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I5S5R1DM		MRA4A0AB	30.04.2010	31.07.2010
MRI3I5S5R2D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I5TA	MRI3I5E5TA		30.04.2010	31.07.2010
MRI3I5TD	MRI3I5TE1D		30.04.2010	31.07.2010
MRI3I5TE1AM		MRI3I1TE1A	30.04.2010	31.07.2010
MRI3I5TE1DM		MRI3I5TE5DM	30.04.2010	31.07.2010
MRI3I5TE1R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I5TE1R1DM		MRA4A0AB	30.04.2010	31.07.2010
MRI3I5TE5AM		MRI3I5TE5A	30.04.2010	31.07.2010
MRI3I5TE5D		IRU1UO1HD	30.04.2010	31.07.2010
MRI3I5TE5R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I5TE5R2D		MRA4A0AA	30.04.2010	31.07.2010
MRI3I5X1DM		MRI3I5X1D	30.04.2010	31.07.2010
MRI3I5X1R1DM		MRI3I5X1R1D	30.04.2010	31.07.2010
MRI3I5X5DM		MRI3I5X5D	30.04.2010	31.07.2010
MRI3I5X5R1DM		MRI3I5X1R1D	30.04.2010	31.07.2010
MRI3S1R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3S5R1D		MRA4A0AA	30.04.2010	31.07.2010
MRI3S5R1DM			30.04.2010	31.07.2010
MRI3X1A		MRI3E1A	30.04.2010	31.07.2010
MRI3X1AM		MRI3E1A	30.04.2010	31.07.2010
MRI3X1D		MRI3I1X1DM	30.04.2010	31.07.2010
MRI3X1DM		MRI3X1D	30.04.2010	31.07.2010
MRI3X1R1A		MRI3I5X1R1A	30.04.2010	31.07.2010
MRI3X1R1AM		MRI3I5X1R1D	30.04.2010	31.07.2010
MRI3X1R1D		MRI3X5R1D	30.04.2010	31.07.2010
MRI3X1R2DM		MRI3I5X1R1D	30.04.2010	31.07.2010
MRI3X1R4A		MRI3I5X1R1A	30.04.2010	31.07.2010
MRI3X1R4D		MRI3I5X1R1D	30.04.2010	31.07.2010
MRI3X5AM		MRI3I1X5A	30.04.2010	31.07.2010
MRI3X5D		MRI3E5D	30.04.2010	31.07.2010
MRI3X5DM		MRI3E5D	30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
MRI3X5R1A		MRI311R1X1R1A	30.04.2010	31.07.2010
MRI3X5R1D		MRI311R1X1R1D	30.04.2010	31.07.2010
MRIK3I1CE1DM		MRIK3I1E1D	30.04.2010	31.07.2010
MRIK3I1CE1R1AM			30.04.2010	31.07.2010
MRIK3I1CE1R2DM			30.04.2010	31.07.2010
MRIK3I1DM	MRIK3I1E1DM		30.04.2010	31.07.2010
MRIK3I1E1A		MRIK3I1E1DM	30.04.2010	31.07.2010
MRIK3I5AM		MRIK3I5E5DM	30.04.2010	31.07.2010
MRIK3I5CE1R1AM			30.04.2010	31.07.2010
MRIK3I5CE1R1DM			30.04.2010	31.07.2010
MRIK3I5CE5DM		MRIK3I5E5DM	30.04.2010	31.07.2010
MRIK3I5CE5R1AM			30.04.2010	31.07.2010
MRIK3I5CE5R1DM			30.04.2010	31.07.2010
MRIK3I5CX1R1DM			30.04.2010	31.07.2010
MRIK3I5D	MRIK3I5E5D		30.04.2010	31.07.2010
MRIK3I5DM	MRIK3I5E5DM		30.04.2010	31.07.2010
MRIK3I5E1A		MRIK3I1E1D	30.04.2010	31.07.2010
MRIK3I5E1AM		MRIK3I5E5DM	30.04.2010	31.07.2010
MRIK3I5E1D		MRIK3I1E1D	30.04.2010	31.07.2010
MRIK3I5E1DM		MRIK3I5E5DM	30.04.2010	31.07.2010
MRIK3I5E5A		MRIK3I5E5DM	30.04.2010	31.07.2010
MRK1A			30.04.2010	31.07.2010
MRK1D		MRIK3I5E5D	30.04.2010	31.07.2010
MRL1110A		MRL1110D	30.04.2010	31.07.2010
MRL1220A		MRL1230D	30.04.2010	31.07.2010
MRL148A		MRL148D	30.04.2010	31.07.2010
MRL1HB220D	MRL1220D		30.04.2010	31.07.2010
MRM32I1A		MRMR32I1E1D	30.04.2010	31.07.2010
MRM32I1AM		MRMR32I1E1DM	30.04.2010	31.07.2010
MRM32I1D	MRM32I1E1D		30.04.2010	31.07.2010
MRM32I1DM	MRM32I1E1DM		30.04.2010	31.07.2010
MRM32I1E1A		MRMR32I1E1D	30.04.2010	31.07.2010
MRM32I5A		MRMR32I5E5D	30.04.2010	31.07.2010
MRM32I5AM		MRMR32I5E5AM	30.04.2010	31.07.2010
MRM32I5D	MRM32I5E5D		30.04.2010	31.07.2010
MRM32I5DAR		MRMR32I5E5D	30.04.2010	31.07.2010
MRM32I5DM	MRMR32I5E5DM		30.04.2010	31.07.2010
MRM32I5E1A		MRM32I1E1D	30.04.2010	31.07.2010
MRM32I5E1AM		MRM32I1E1DM	30.04.2010	31.07.2010
MRM32I5E1D		MRM32I5E1DM	30.04.2010	31.07.2010
MRM32I5E5A		MRM32I5E5D	30.04.2010	31.07.2010
MRN311AM		MRU4A0AB	30.04.2010	31.07.2010
MRN312A		MRN3211A	30.04.2010	31.07.2010
MRN312D		MRN3211D	30.04.2010	31.07.2010
MRN312DM		MRN311DM	30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
MRN314AM		MRN321A	30.04.2010	31.07.2010
MRN321AM		MRN321A	30.04.2010	31.07.2010
MRN322A		MRN321A	30.04.2010	31.07.2010
MRN322D		MRN321D	30.04.2010	31.07.2010
MRN324DM		MRN324D	30.04.2010	31.07.2010
MRN331A		MRU4A0BA	30.04.2010	31.07.2010
MRN331DM		MRU4A0AB	30.04.2010	31.07.2010
MRN331DM		MRU4A0AB	30.04.2010	31.07.2010
MRN334DM		MRU4A0AB	30.04.2010	31.07.2010
MRP21I1U1A		MRP23I5U1D	30.04.2010	31.07.2010
MRP21I1U1D		MRP23I5U1DM	30.04.2010	31.07.2010
MRP21I1U1DM		MRP23I5U1DM	30.04.2010	31.07.2010
MRP21I1U2A		MRP23I5U1DM	30.04.2010	31.07.2010
MRP21I1U2D		MRP23I5U1DM	30.04.2010	31.07.2010
MRP21I1U4A		MRP23I5U4D	30.04.2010	31.07.2010
MRP21I1U4D		MRP23I5U4D	30.04.2010	31.07.2010
MRP21I5U1A		MRP23I5U1DM	30.04.2010	31.07.2010
MRP21I5U1D		MRO23U5R1DM	30.04.2010	31.07.2010
MRP21I5U1DM		MRP23I5U1DM	30.04.2010	31.07.2010
MRP21I5U2A		MRP23I5U1DM	30.04.2010	31.07.2010
MRP21I5U2D		MRP23I5U1DM	30.04.2010	31.07.2010
MRP21I5U4A		MRP23I5U4D	30.04.2010	31.07.2010
MRP21I5U4D		MRP23I5U4D	30.04.2010	31.07.2010
MRP23I1U1A		MRP23I5U1D	30.04.2010	31.07.2010
MRP23I1U1D		MRP23I5U1DM	30.04.2010	31.07.2010
MRP23I1U1DM		MRP23I5U1DM	30.04.2010	31.07.2010
MRP23I1U2A		MRP23I5U1DM	30.04.2010	31.07.2010
MRP23I1U2D		MRP23I5U1DM	30.04.2010	31.07.2010
MRP23I1U4A		MRP23I5U4D	30.04.2010	31.07.2010
MRP23I1U4D		MRP23I5U4D	30.04.2010	31.07.2010
MRP23I5U1A		MRP23I5U1DM	30.04.2010	31.07.2010
MRP23I5U1D		MRP23I5U1DM	30.04.2010	31.07.2010
MRP23I5U2A		MRP23I5U1DM	30.04.2010	31.07.2010
MRP23I5U2D		MRP23I5U1DM	30.04.2010	31.07.2010
MRP23I5U2DM		MRP23I5U1D	30.04.2010	31.07.2010
MRP23I5U4A		MRP23I5U4D	30.04.2010	31.07.2010
MRP23I5U4DM		MRP23I5U1D	30.04.2010	31.07.2010
MRP2R1I1U1A		MRP2R3I1U1A	30.04.2010	31.07.2010
MRP2R1I1U1AM		MRP2R3I1U1A	30.04.2010	31.07.2010
MRP2R1I1U1D		MRP2R3I1U1D	30.04.2010	31.07.2010
MRP2R1I1U2A		MRP2R3I1U1A	30.04.2010	31.07.2010
MRP2R1I1U2D		MRP2R3I1U1D	30.04.2010	31.07.2010
MRP2R1I1U4A		MRP2R3I1U1A	30.04.2010	31.07.2010
MRP2R1I1U4D		MRP2R3I1U1D	30.04.2010	31.07.2010
MRP2R1I5U1A		MRP2R3I5U1A	30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
MRP2R1I5U1AM		MRP2R3I5U1A	30.04.2010	31.07.2010
MRP2R1I5U1D		MRP2R3I5U1D	30.04.2010	31.07.2010
MRP2R1I5U1DM		MRP2R3I5U1D	30.04.2010	31.07.2010
MRP2R1I5U2A		MRP2R3I5U1A	30.04.2010	31.07.2010
MRP2R1I5U2D		MRP2R3I5U1D	30.04.2010	31.07.2010
MRP2R1I5U4A		MRP2R1I5U1A	30.04.2010	31.07.2010
MRP2R1I5U4AM		MRP2R3I5U1A	30.04.2010	31.07.2010
MRP2R1I5U4D		MRP2R3I5U1D	30.04.2010	31.07.2010
MRP2R3I1U1AM		MRP2R3I1U1A	30.04.2010	31.07.2010
MRP2R3I1U1DM		MRP2R3I1U1D	30.04.2010	31.07.2010
MRP2R3I1U2A		MRP2R3I1U1A	30.04.2010	31.07.2010
MRP2R3I1U2D		MRP2R3I1U1D	30.04.2010	31.07.2010
MRP2R3I1U4A		MRP2R3I1U1A	30.04.2010	31.07.2010
MRP2R3I1U4D		MRP2R3I1U1D	30.04.2010	31.07.2010
MRP2R3I5U1DM		MRP2R3I5U1D	30.04.2010	31.07.2010
MRP2R3I5U2A		MRP2R3I5U1A	30.04.2010	31.07.2010
MRP2R3I5U2D		MRP2R3I5U1D	30.04.2010	31.07.2010
MRP2R3I5U2DM		MRP2R3I5U1D	30.04.2010	31.07.2010
MRP2R3I5U4A		MRP2R3I5U1A	30.04.2010	31.07.2010
MRP2R3I5U4AM		MRP2R3I5U1A	30.04.2010	31.07.2010
MRP2R3I5U4D		MRP2R3I5U1D	30.04.2010	31.07.2010
MRP2R3I5U4DM		MRP2R3I5U1D	30.04.2010	31.07.2010
MRP2S3I1U1A			30.04.2010	31.07.2010
MRP2S3I1U1D			30.04.2010	31.07.2010
MRP2S3I1U1DM			30.04.2010	31.07.2010
MRP2S3I5U1D			30.04.2010	31.07.2010
MRP2S3I5U1DM			30.04.2010	31.07.2010
MRP2S3I5U4D			30.04.2010	31.07.2010
MRQ1I1U2A		MRQ1I1U1A	30.04.2010	31.07.2010
MRQ1I1U2D		MRQ1I1U1D	30.04.2010	31.07.2010
MRQ1I1U4A		MRQ1I1U1A	30.04.2010	31.07.2010
MRQ1I1U4D		MRQ1I5U4D	30.04.2010	31.07.2010
MRQ1I5U2A		MRQ1I5U1A	30.04.2010	31.07.2010
MRQ1I5U2D		MRQ1I5U4D	30.04.2010	31.07.2010
MRQ1I5U4A		MRQ1I5U1A	30.04.2010	31.07.2010
MRU122D		MRU321D	30.04.2010	31.07.2010
MRU311AM		MRU311A	30.04.2010	31.07.2010
MRU312A		MRU311A	30.04.2010	31.07.2010
MRU312D		MRU314DM	30.04.2010	31.07.2010
MRU312DM		MRU311DM	30.04.2010	31.07.2010
MRU314A		MRU311A	30.04.2010	31.07.2010
MRU314D		MRU311D	30.04.2010	31.07.2010
MRU321AM		MRU321A	30.04.2010	31.07.2010
MRU322D		MRU321D	30.04.2010	31.07.2010
MRU322DM		MRU321DM	30.04.2010	31.07.2010

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
MRU324A		MRU321A	30.04.2010	31.07.2010
MRU324D		MRU4A0AB	30.04.2010	31.07.2010
MRU324DM		MRU321DM	30.04.2010	31.07.2010
RSC2NT1230			30.04.2010	31.07.2010
RSC2RS4851		RSC2RS4855	30.04.2010	31.07.2010

Parts set to inactive directly

Part number	Replacement	Replacement /Similar item
MRD1VAC1		
MRD1VAC2		
MRD1VAC4		
MRI3I5CE1R1DM		MRI3I5R1E1R1D
MRI3I5CE5R1DM		MRI3I5R1E5R1D
MRI3I5CX1R1DM		MRI3I1R1X1R1D
MRT12BD		
MSC20114CM		
RS485TR		

6 WI - Line

Parts to be discontinued

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
WI1310WE1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI1310WR1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI1311WE1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI1311WE1A		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI1313WR1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI1314WE1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI1315WE1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI133WE1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI133WR1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI134WR1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI137WE1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI138WE1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI139WR1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WI23WE1		WIC12PE + WI1WIC1ADAP	30.04.2010	31.07.2010
WIC11P	WIC11PE		30.04.2010	31.07.2010
WIC11PW	WIC11PEW		30.04.2010	31.07.2010
WIC12P	WIC12PE		30.04.2010	31.07.2010
WIC12PW	WIC12PEW		30.04.2010	31.07.2010
WIC13P	WIC13PE		30.04.2010	31.07.2010
WIC14P	WIC14PE		30.04.2010	31.07.2010
WIM1S1RM1			30.04.2010	31.07.2010
WIM1S5RM1			30.04.2010	31.07.2010
WIP11I1	WIP11I1E1		30.04.2010	31.07.2010
WIZ1C1EL1			30.04.2010	31.07.2010
WIZ1C1EL21			30.04.2010	31.07.2010
WIZ1C1RK1			30.04.2010	31.07.2010
WIZ1C1RK21			30.04.2010	31.07.2010
WIZ1C1RL1			30.04.2010	31.07.2010
WIZ1C5EL1			30.04.2010	31.07.2010
WIZ1C5EL21			30.04.2010	31.07.2010
WIZ1C5RK1			30.04.2010	31.07.2010
WIZ1C5RK21			30.04.2010	31.07.2010
WIZ1C5RL1			30.04.2010	31.07.2010
WIZ1S1RK1			30.04.2010	31.07.2010
WIZ1S1RK21			30.04.2010	31.07.2010
WIZ1S1RL1			30.04.2010	31.07.2010
WIZ1S5RK1			30.04.2010	31.07.2010
WIZ1S5RK21			30.04.2010	31.07.2010
WIZ1S5RL1			30.04.2010	31.07.2010

Parts set to inactive directly

Part number	Replacement	Replacement /Similar item
WIC1HB42W2		
WIC1HB42W3		
WIC1HB42W4		
WIC1HB42W5		
WIM1H1EL2		WIP1I1E1

7 System - Line

Parts to be discontinued

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
CMP121M		CMP120	30.04.2010	31.07.2010
CSP2F3SCC00E		CSP2F5SCC00E	30.04.2010	31.07.2010
CSP2F3SCC00E1		CSP2F5SCC00E1	30.04.2010	31.07.2010
CSP2F3SCC00EK		CSP2F5SCC00EK	30.04.2010	31.07.2010
CSP2F3SCC00G		CSP2F5SCC00G	30.04.2010	31.07.2010
CSP2F3SCC3FE		CSP2F5SCC3FE	30.04.2010	31.07.2010
CSP2F3SCC3FG		CSP2F5SCC3FG	30.04.2010	31.07.2010
CSP2F3SCC3FGK		CSP2F5SCC3FGK	30.04.2010	31.07.2010
CSP2F3SCC3WE		CSP2F5SCC3WE	30.04.2010	31.07.2010
CSP2F3SCC3WG		CSP2F5SCC3WG	30.04.2010	31.07.2010
CSP2F3SCCMFE		CSP2F5SCCMFE	30.04.2010	31.07.2010
CSP2F3SCCMFEK		CSP2F5SCCMFEK	30.04.2010	31.07.2010
CSP2F3SCCMFG		CSP2F5SCCMFG	30.04.2010	31.07.2010
CSP2F3SCCMWE		CSP2F5SCCMWE	30.04.2010	31.07.2010
CSP2F3SCCMWEK		CSP2F5SCCMWEK	30.04.2010	31.07.2010
CSP2F3SCCMWG		CSP2F5SCCMWG	30.04.2010	31.07.2010
CSP2F3SCCMWGK		CSP2F5SCCMWGK	30.04.2010	31.07.2010
CSP2F3SCCPFE		CSP2F5SCCPFE	30.04.2010	31.07.2010
CSP2F3SCCPFG		CSP2F5SCCPFG	30.04.2010	31.07.2010
CSP2F3SCCPFGK		CSP2F5SCCPFGK	30.04.2010	31.07.2010
CSP2F3SCCPWE		CSP2F5SCCPWE	30.04.2010	31.07.2010
CSP2F3SCCPWEK		CSP2F5SCCPWEK	30.04.2010	31.07.2010
CSP2F3SCCPWG		CSP2F5SCCPWG	30.04.2010	31.07.2010
CSP2F3SCCPWGK		CSP2F5SCCPWGK	30.04.2010	31.07.2010
SLDOKHBBE			30.04.2010	31.07.2010
SLDOKHBBG			30.04.2010	31.07.2010
SLDOKHBF/LE			30.04.2010	31.07.2010
SLDOKHBF/LG			30.04.2010	31.07.2010
SLDOKHBSE			30.04.2010	31.07.2010
SLDOKHBSG			30.04.2010	31.07.2010
SLDOKHBTE			30.04.2010	31.07.2010
SLDOKHBTG			30.04.2010	31.07.2010

Parts set to inactive directly

Part number	Replacement	Replacement / Similar item
CMP1121H		CMP1-120
CMP1121M		CMP1-120
CMP1121O		CMP1-120
CMP1220		CMP1-120
CSP1B061C1H3FE		
CSP1B061C1H3FG		

Part number	Replacement	Replacement /Similar item
CSP1B061C5H3FE		
CSP1B061C5L3FE		
CSP1B061C5L3FG		
CSP1B181C1H3FE		
CSP1B181C1H3FG		
CSP1B181C1M3FE		
CSP1F1CH00E		CSP2F5SCC00E
CSP1F1CH00G		CSP2F5SCC00G
CSP1F1CHV3E		CSP2F5SCC3FE
CSP1F1CHV3G		CSP2F5SCC3FG
CSP1F1CL00E		CSP2F5SCC00E
CSP1F1CL00G		CSP2F5SCC00G
CSP1F1CLV3E		CSP2F5SCC3FE
CSP1F1CLV3G		CSP2F5SCC3FG
CSP1F3CH00E		CSP2F5SCC3FE
CSP1F3CH00G		CSP2F5SCC00G
CSP1F3CH00GK		CSP2F5SCC00GK
CSP1F3CHV3E		CSP2F5SCC3FE
CSP1F3CHV3EK		CSP2F5SCC3FEK
CSP1F3CHV3G		CSP2F5SCC3FG
CSP1F3CHV3GK		CSP2F5SCC3FGK
CSP1F3CL00E		CSP2F5SCC00E
CSP1F3CL00G		CSP2F5SCC00G
CSP1F3CLV3E		CSP2F5SCC3FE
CSP1F3CLV3EK		CSP2F5SCC3FEK
CSP1F3CLV3G		CSP2F5SCC3FG
CSP1F3CLV3GK		CSP2F5SCC3FGK
CSP1F5CH00E		CSP2F5SCC00E
CSP1F5CH00G		CSP2F5SCC00G
CSP1F5CHV3E		CSP2F5SCC3FE
CSP1F5CHV3EK		CSP2F5SCC3FEK
CSP1F5CHV3G		CSP2F5SCC3FG
CSP1F5CHV3GK		CSP2F5SCC3FGK
CSP1F5CL00E		CSP2F5SCC00E
CSP1F5CL00G		CSP2F5SCC00G
CSP1F5CLV3E		CSP2F5SCC3FE
CSP1F5CLV3EK		CSP2F5SCC3FEK
CSP1F5CLV3G		CSP2F5SCC3FG
CSP1F5CLV3GK		CSP2F5SCC3FGK
CSP1L21CH001E		CSP2L1SCC00E
CSP1L21CH001G		CSP2L1SCC00G
CSP1L21CH002E		CSP2L2SCC00E
CSP1L21CHV31E		CSP2L1SCC3FE
CSP1L21CHV31G		CSP2L2SCC3FG
CSP1L21CHV32E		CSP2L2SCC3FE

Part number	Replacement	Replacement /Similar item
CSP1L21CHV32EK		CSP2L2SCC3FEK
CSP1L21CLV31E		CSP2L1SCC3FE
CSP1L21CLV31G		CSP2L1SCC3FG
CSP1LS1CH001E		CSP2L1SCC00E
CSP1LS1CH001G		CSP2L1SCC00G
CSP1LS1CH002E		CSP2L2SCC00E
CSP1LS1CHV31E		CSP2L1SCC3FE
CSP1LS1CHV31G		CSP2L1SCC3FG
CSP1LS1CHV32E		CSP2L2SCC3FE
CSP1LS1CHV32EK		CSP2L2SCC3FEK
CSP1LS1CLV31E		CSP2L1SCC3FE
CSP1LS1CLV31G		CSP2L1SCC3FG
CSP2F3CC00E		CSP2F5SCC00E
CSP2F3CC00G		CSP2F5SCC00G
CSP2F3CC3FE		CSP2F5SCC3FE
CSP2F3CC3FG		CSP2F5SCC3FG
CSP2F3CC3FGK		CSP2F5SCC3FGK
CSP2F3CC3WE		CSP2F5SCC3WE
CSP2F3CC3WG		CSP2F5SCC3WG
CSP2F3CCMFGK		CSP2F5SCCMFGK
CSP2F3CCMWE		CSP2F5SCCMWE
CSP2F3CCMWGK		CSP2F5SCCMWGK
CSP2F3CCPFE		CSP2F5SCCPFE
CSP2F3CCPFG		CSP2F5SCCPFG
CSP2F3CCPFGK		CSP2F5SCCPFGK
CSP2F3CCPWE		CSP2F5SCCPWE
CSP2F3CCPWG		CSP2F5SCCPWG
CSP2F3SCC00GK		CSP2F5SCC00GK
CSP2F5CC3FE		CSP2F53SCC3FE
CSP2F5CC3FG		CSP2F5SCC3FG
CSP2F5CC3WEK		CSP2F5SCC3WEK
CSP2F5CCPFGK		CSP2F5SCCPFGK
CSP2F5CCPWE		CSP2F5SCCPWE
CSP2F5CCPWG		CSP2F5SCCPWG
CSP2L1CC00G		CSP2L1SCC00G
CSP2L1CC00GK		CSP2L1SCC00GK
CSP2L1CC3FE		CSP2L1SCC3FE
CSP2L1CC3FG		CSP2L1SCC3FG
CSP2L1CC3FGK		CSP2L1SCC3FGK
CSP2L1CC3WG		CSP2L1SCC3WG
CSP2L1CCMFG		CSP2L1SCCMFG
CSP2L1CCMWG		CSP2L1SCCMWG
CSP2L1CCPFG		CSP2L1SCCPFG
CSP2L1CCPWG		CSP2L1SCCPWG
CSP2L2CC00E		CSP2L2SCC00E
CSP2L2CC3FE		CSP2L2SCC3FE
CSP2L2CC3FG		CSP2L2SCC3FG

8 HighPROTEC

Parts set to inactive directly

Part number	Replacement
MRA4A0A0A0A0A0	MRA4A0AA
MRA4A0A0A0A0A1	MRA4A0AA
MRA4A0A0A0A0G0	MRA4A0AG
MRA4A0A0A0A0H0	MRA4A0AB
MRA4A0A1A0A0G0	MRA4A0AG
MRA4A0A1A0A0H0	MRA4A0AB
MRA4C0A0A0A0A0	MRA4D0AA
MRA4C0A0A0A0G0	MRA4D0AG
MRA4C0A0A0A0H1	MRA4D0AB
MRA4C0A1A0A0G0	MRA4D0AG
MRA4C0A1A0A0H0	MRA4D0AB
MRA4D0A0A0A0G0	MRA4D0AG
MRA4D0A1A0A0G1	MRA4D0AG
MRA4D0A1A0A0H1	MRA4D0AB
MRI4A0A0A0A0A0	MRI4A0AA
MRI4A0A0A0A0A1	MRI4A0AA
MRI4A0A0A0A0F1	MRI4A0AF
MRI4A0A0A0A0H0	MRI4A0AB
MRI4A0A1A0A0C0	MRI4A0AG
MRU4A0A0A0A0G0	MRU4A0AG
MRU4A0A0A0A0H0	MRU4A0AB

9 Power Protection Aux.

Parts to be discontinued

Part number	Replacement	Replacement / Similar item	Date of LTB stop	Date of production stop
COMMOD1			30.04.2010	31.07.2010
COMMOD2			30.04.2010	31.07.2010
RSC24852321		RSC2485USB1	30.04.2010	31.07.2010
WIC1W3H1		WIC1W3AS1	30.04.2010	31.07.2010
WIC1W4H1		WIC1W4AS1	30.04.2010	31.07.2010
WIC1W5H1		WIC1W5AS1	30.04.2010	31.07.2010
WIC1WE2H1		WIC1WE2AS1	30.04.2010	31.07.2010

Parts set to inactive directly

Part number	Replacement	Replacement / Similar item
BL40400		BL40400
COMRS232PC3		
MPU1FI1CAN		8444-1015
MPU1FI1MOD		8444-1017
MPU1FI5CAN		8444-1014
MPU1FI5MOD		8444-1016
MPU2PI1U1P10		8444-1776
MPU2SI1U1H		8444-1127
MPU2SI1U1L		8444-1172
MPU2SI1U1M		8444-1124
MPU2SI1U4H		8444-1256
MPU2SI1U4L		8444-1174
MPU2SI5U1H		8444-1255
MPU2SI5U1L		8444-1255
MPU2SI5U1M		8444-1173
MPU2SI5U4H		8444-1128
MPU2SI5U4L		8444-1123
MPU2SI5U4M		8444-1126
MS1DR		8923-1023
SG11		8923-1036
SG12		8923-1037
SG13		8923-1039
SG14		8923-1043
TZR1		
USBRS232ADAPTER		USBRS232ADAP
WI1SZ2		WI1SZ4
WI2W202		
WIC1HP		
WIC1W2H1		WIC1W2H1
WIC1W3H1		WIC1W3AS1
XD1GW1351	XD1GW1353	
XD1GW1352	XD1GW1354	